

2-4

25

参数	工作温度 (°C)	湿度	温度 (°C)	存储相对湿度 (%)	引脚焊接温度 (max/°C)
最小	10	-	-20	-	-
最大	30	75	70	90	250(10Sec.)



* D -
* P -
FS -

mm

